http://www.eresnet.com



-LTPP Seasonal Monitoring Program

Site Monitoring Suspension Status Draft Final Report for GPS Section 271028 (27B) Detroit Lakes, Minnesota

Research

Pavement Management Systems

Evaluation & Design Services

Technology Transfer

Software Services & Products

LTPP Seasonal Monitoring Program

Site Monitoring Suspension Status Draft Final Report for GPS Section 271028 (27B) Detroit Lakes, Minnesota

FHWA CONTRACT No. DTFH61-96C-00013

Prepared by

ERES Consultants, Inc. 505 West University Avenue Champaign, IL 61820

Prepared for

Federal Highway Administration LTPP Division, HNR-40 Turner-Fairbanks Highway Research Center 6300 Georgetown Pike McLean, Virginia 22101-2296

November 1997

Technical Report Documentation Page

1. Report No.	2. Government Acce	ssion No.	3. Recipient's Catalo	g No.
FHWA-				
4. Title and Subtitle	<u> </u>		5. Report Date	
LTPP Seasonal Monitoring Prog			February 3, 199	8
Report for GPS Section 271028(2	7B) Detroit Lakes	, Minnesota		
			6. Performing Organ	nization Code
7. Author(s)	7119 _ 44		8. Performing Organ	nization Report No.
Robert Kumapley and Graden I				
9. Performing Organization Name and Ad ERES Consultants, Inc.	dress		10. Work Unit No.	
505 West University Avenue				
Champaign, Illinois 61820-3915				
C			11. Contract or Gran	it No.
			DTFH61-96-C-0	
12. Sponsoring Agency Name and Address	<u> </u>		13. Type of Report a	nd Period Covered
Federal Highway Administration			,, ,	
LTPP Division, HNR-40				
Turner-Fairbanks Highway Rese	earch Center		Final Report	
6300 Georgetown Pike			Oct. 1997 to Sep	ot. 1998
McLean, Virginia 22101-2296			14 Spannaning Ages	m. Codo
			14. Sponsoring Ager	icy Code
15. Supplementary Notes				
FHWA LTPP Technical Represer	ntativa Azamia T	oner UND 40		
riiwa Liii Technicai Kepiesei	illative - Atantis i	Lopez, HIAR-40		
TC Abeliand				
16. Abstract				
This report contains information	on suspension o	f NCRCO's data	collection activit	ies for the Long
Term Pavement Performance (L)				
September 10, 1997. The report j		•		
collection activities, including e				
suspension of data collection, an				
monitoring at this site is schedu	led for Septembe	r, 1998. All instr	umentation at the	site will be
tested at that time.				
17. Keyword	I TOP	18. Distribution State		** 1 1 4
Long Term Pavement Performan	•		This document i	
Seasonal Monitoring Program, S Domain Reflectometry, TDR, Pic		are hanne mom	the sponsoring a	igency.
Falling Weight Deflectometer	CEOHICUL,			
19. Security Classification (of this report)	Security Classification	on (of this page)	21. No. of Pages	22. Price
Unclassified	Unclassified	-	-	
	l .			

Table of Contents

	Page
TECHNICAL REPORT DOCUMENTATION PAGE	i
1.0 INTRODUCTION	1
2.0 SMP DATA COLLECTION	2
2.1 SMP Data Collection and Upload	2
2.2 Instrument and Equipment Problems	3
3.0 INSTRUMENT DE-INSTALLATION ACTIVITIES	3
3.1 Suspension Preparation and Repairs to Instrumentation Hole	3
3.2 Unique Site Features	4
4.0 INSTRUMENT REINSTALLATION	4
5.0 SUMMARY	4
LIST OF REFERENCES	5
APPENDIXES	
Appendix A - SMP Data Collection Summary Table	
Appendix B - SMP Data Sheets	
Appendix C- Site Information Sheet (SIS)	

LTPP Seasonal Monitoring Program
Site Monitoring Suspension Status
Draft Final Report for
GPS Section 271028 (27B)
Detroit Lakes, Minnesota

1.0 INTRODUCTION

As dictated by seasonal monitoring procedures, the North Central Regional Coordination Office (NCRCO) has suspended data collection for the Long Term Pavement Performance (LTPP) General Pavement Study (GPS) section 271028 for a period of one year, effective September 10, 1997. The test section, which is part of the Seasonal Monitoring Program (SMP) managed by the Federal Highway Administration (FHWA) LTPP Division, is approximately 21 kilometers east of Detroit Lakes, Minnesota, on the eastbound driving lanes of US Highway 10. Additional background information on the test section, types of instruments installed, and the in-place pavement structure can be found in the Site Installation Report for GPS Section 271028 (27A), Detroit Lakes, Minnesota, dated January 1996 (1).

This report contains information on site monitoring suspension and data collection activities conducted on September 10, 1997. After the installation of instrumentation in the test section on September 8, 1993, the test section was visited 27 times for SMP data collection by Braun Intertec, until June 14, 1995.

The test section was then visited 8 times for onsite SMP data collection by MN-DOT. Beginning October 8, 1996, the site was visited 14 times for SMP data collection by ERES Consultants. Following the ERES site visit of July 9, 1997, the test section was overlayed, and data collection on subsequent visits was limited to onsite, mobile and water table measurements. As of September 10, 1997, MN-DOT has assumed SMP data collection from the site, until September 1998, after which ERES Consultants will monitor the site for another year. The dates of these visits and the activities performed can be found in the SMP data collection summary table in appendix A. This section is planned to be monitored every other year for the remainder of the LTPP study or until it is removed from the study.

The report presents a description of the following activities: SMP data collection activities, including evaluation of instrument and equipment performance prior to suspension of monitoring, and schedule for resumption of monitoring.

2.0 SMP DATA COLLECTION

2.1 SMP Data Collection and Upload

On ERES Consultants' last site visit of September 10, 1997, data collection consisted of onsite, mobile and water table data. The full suite of SMP monitoring measurements in the LTPP Seasonal Monitoring Program Instrument Installation and Data Collection Guidelines (2) was not performed prior to the

overlay of the site, as ERES was not informed of the the overlay. New layer thickness data is currently being investigated.

A summary of all the SMP data collected to date can be found in the SMP data collection summary table in appendix A. The specific type and amount of data collected can be found on the SMP field activity report (data sheet SMP-D10) in appendix B.

2.2 Instrument and Equipment Problems

All the sensors in the test section (TDR, rain gauge, and Measurement Research Corporation [MRC]) were evaluated by reviewing the data from the onsite and mobile dataloggers using the SMPCheck 2.5c program (3). A review of the data collected during this visit indicated that all sensors are functioning properly. The TDR traces all have the maximum and minimum points on the traces that enable analysis.

3.0 INSTRUMENT DE-INSTALLATION ACTIVITIES

3.1 Suspension Preparation and Repairs to Instrumentation Hole

All instrumentation remains installed at this site. The instrument block is in excellent condition, having been overlayed in July of 1997.

3.2 Unique Site Features

This test section is the 2nd SMP installation in the LTPP North Central Region.

In the course of monitoring this site, a solar panel was installed on top of the cabinets to prolong the life of the battery onsite. The solar panel was found to be an effective and significant addition to the SMP onsite data collection equipment that ensured efficient storage and collection of the SMP data stored onsite.

4.0 INSTRUMENT REINSTALLATION

All instrumentation remains installed at this site. Resumption of SMP monitoring by ERES Consultants is scheduled for September, 1998, assuming the section remains in study following the overlay, pending the recommendations of PCS/Law and FHWA.

5.0 SUMMARY

This report contains information on data collection activities for the LTPP GPS section 271028, conducted on September 10, 1997. The report presents a description of the SMP data collection activities, including an evaluation of the SMP sensors and equipment. No problems were noted from the onsite data recorded from August 14, 1997, through September 10, 1997. The TDR traces all have the required maximum and minimum points that enable analysis of the TDR data.

Resumption of monitoring at this site by ERES Consultants is scheduled for September, 1998.

LIST OF REFERENCES

- LTPP Seasonal Monitoring Program Site Installation Report for GPS Section 271028 (27B) Detroit Lakes, Minnesota, Federal Highway Administration, LTPP Division, HNR-40, Turner-Fairbanks Highway Research Center, McLean, Virginia. January 1996.
- LTPP Seasonal Monitoring Program: Instrumentation Installation and Data
 Collection Guideline. FHWA-RD-94-110, Federal Highway Administration,
 LTPP Division, HNR-40, Turner-Fairbanks Highway Research Center,
 McLean, Virginia. April 1994.
- SMPCheck, computer software version 2.5c, prepared for the Federal Highway Administration, Pavement Performance Division, HNR-30, McLean, Virginia. July 1997.
- 4. Lopez, Aramis, Jr. Long Term Pavement Performance Directive for the Seasonal

 Monitoring Program: Directive Number SM-8, Suspension of SMP Site Monitoring

 Activities. Federal Highway Administration, LTPP Division, HNR-40, TurnerFairbanks Highway Research Center, McLean, Virginia. March 1995.

Appendix A - SMP I	nmary Table	

							27SB :	271028	27SB - 271028, US-10 EB LANES, 13 MILES EAST OF DETROIT LAKES, MN (MP 58.	B LAN	IES, 13	MILES	EAST	OF DE	TROIT	LAKES	MN (/P 58.3	3			,	
		ı	PIISNO	E Data	١	МОВ	MOBILE Data	a			Manual Data	Data		İ	Ţ	FWD Data	а		Distress I Profile	S Pro	e		
	Date dd/mmm/yy	<u> </u>	Pvmt. Temp.	Air Temp	Rain	HQT	Frost Votts	Backup TDR	Backup TDR	Frost 2-Pt.	Frost 4-Pt.		Pvmt.	Joint t	Joint T	Man. Temp.	₽	ML PE	∡	- -	0	Comments	
	1-Nov-92												***		-		_		4				
_	1-Jun-93	T	H										***							×			
_	27-Jul-93	1						建筑设施					***						X		(8) (8)		
_	8-Sep-93	93	1													*		_				INSTALLATION, MANUAL TDR DATA.	
_	9-585-93	938										3,00	~ **			×	4	**************************************		_		NO RESISTIVITY SWITCH BOX	
_	20-001-93	930											***		8	×	_	<u> </u>				NO RESISTIVITY SWITCH BOX	
_	18-Nov-93	930							经信息 量量			P	÷			×	ુ	3	_			ADDED KELAY TO ONSITE, TWO FILES FOR THE DAY.	
_	20-Nov-93				Γ		L						***							×			
_	8-000-93	935										•	~			>		**			95. 65.	BAD RESISTIVITY SWITCH BOX	
_	0-Fah-04	944	,													2				\vdash	1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1	BAD RESISTIVITY SWITCH BOX	
	17-1-65-04	1	100000000000000000000000000000000000000								2					L	L		L	-			
_	9-Mar-94	4									2	•		ı		L	L						
	23-Mar-94	9 2										_	- -			د ب			Ž	\dagger		MANUAL READING ON TUR #1, ODD TRACE.	
	5-Apr-94	94									-		***			, ,		,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	+	\dagger		PAD RESIDITATION IN	
	20-Apr-94								100 110 110 110 110 110 110 110 110 110								_		-	×			
	26-Apr-94	945									-	P	***			X	_	<u></u>					
_	IO-May-94	4	Ì										 			<u>بر</u>		+					
_	14-3011-94	2 4		Ī								F				. ,	<u>1</u> 2			H	5		
_	78-11-04	14	-													ż				-			
	9-Aug-94	8								ē						L	L			*	100		
_	19-Sep-94	94									200		**						1	\dagger		PROBLEMAL FILL FOUND, DOWNLOADED PROGRAM AGAINS	CALINY
_	29-Sep-94	Н														1	-		1		27 0		
_	11-0a-94	94								_			***		*	×		**	_				
_	0-IV0V-94	¥4.8	\$					No.					 **			,	3 3						
_	10-Jan-95	954		I						= =	-			L		بر ب	 		L	H			
	20-Jan-95	1																	1			PROPILE DATA NOT RECEIVED BY BOO	
	7-Feb-95	958	3	***************************************	**	8		*H\$0.00	第一条 4	Ę	=	i.				4	\parallel					WEATHER REDUCED TESTING, CAP FROZE ON PIEZOMETER	
_	8-Mar-95	950							的第四人		=	1									推		
_	21-Mar-95	200							经验证据	1	-		~			×	ن ز		×	Н	F R	REPLACED METAL COVER ON PEEZOMETER.	
_	18-401-95	9 9								3 -						_				_	100		
_	22-Apr-95	2							SHALL NO.					L		ž						7.7.	
_	9-May-95	925	11						COMPANY OF THE PROPERTY OF THE							L	-					WEATHER REDUCED TESTING, BY PIN ON RESISTIVITY CABLE REPAIRED.	REPAIRED.
_	15-May-95	9 2	Ì							3 -	÷ ~			l			L			\dagger			
	14-Jun-95	95								•		-	÷.			ر ب	. i		-				
	2/-Jun-95	H															_		1				
,						I				l													

Notes

P Denotes data collected and processed by Braun Intertec Corp
P Denotes data collected and processed by ERES Consultants, Inc
Denotes data collected by Braun Intertec Corp.
X Denotes data collected by ERES Consultants, Inc.
X Denotes data collected by Braun Intertec Corp. and processed by ERES Consultants, Inc.
X Denotes data collected and processed by SME

	is.	1	-		4	\parallel				-	-	-										
	130 130	1	-			4				-	-											
			4		_													_			H	
		┪	\dashv	***														H			H	
		H	Ц		L	-				-	_		*					H		Ī	H	
		Н	Н							\vdash	L	H									l	
	(E)											-	188	相 医眼样 物				-		Ī	H	
					Ц					\vdash	-	L		200				r	l	Ī	-	
	10 11 50									L	-	<u> </u>						H	_		H	
		Н			Н	L				-	-	-						\vdash			ŀ	
					L	L							1000 1000 1000 1000 1000 1000 1000 100						İ	İ	H	
			_		L	_				L	_				THE WATER			f	İ	Ī	H	
			L		L					ŀ	70			B. 185.781		P	7	7	-	-	9/K	10-Sep-9/
Site overlayed	S	Н	L		L	L				ŀ	 -	L	- 65			7	7	1	-	T	L	14-Aug-9/
Mobile CR10 not working		Н	Ц	***	3 3	X				٦	_ _	-						\vdash	-	Γ	ட	9-Jul-9/
No traffic control	7		Ц		L	H				H	\vdash	T	##			7	7	7	-	Γ	1/9/H	12-Jun-9/
, , , , , , , , , , , , , , , , , , ,	ē.		Ц		Н	X				P	Н	H				ъ	ס	70	70	Π	Ľ	30-May-97
		Н			3 3					L	P	H	P			Р	v	0	70	Γ	1	8-May-97
					4 4	X				P	P	Н	OR HELD			Р	Р	ס	7	Γ	L.,	24-Apr-97
	351 1	\forall	-			_						Н	N.		STEPPER THE STATE					Γ		22-Apr-97
	W.				2 2	X				ď	P	P	P			Р	ס	פ	7	70	97D	10-Apr-97
Couldn't find piezo.	D.H.J.C.	1	\dashv		4 4	×						d l	P	建海绵气		P		-	7	Γ		20-Mar-97
Mobile cabinet had power failure		1	\dashv							d	P	Н	THE STATE OF THE S					P	70			3-Feb-97
		\times			\dashv					_								H			ľ	19-Jan-97
		+	-		4													ס	P	P	97A	9-Jan-97
	86 84	1	4		4					\dashv		J	P			Р	P	P	P		Ш	5-Dec-96
	ă.	1	-		2				1	J	٦	٦	P			q	ъ	U	þ	P		5-Nov-96
	565 177	+	+		4	ĭ				P	J	J	P			Р	P	р	P			8-Oct-96
		+	+		+					\dashv	\dashv	+			22			Z	X	×		17-Aug-96
	N.	+	+		+	\parallel				-	-	\dashv						≤	×	Z		29-Jun-96
		+	+		+	-				\dashv	\dashv	\dashv	ile.	200				×	∡		960	14-May-96
		+	+		4	+				\dashv	+	\dashv		-				≤	×			19-Feb-96
		+	+		\dashv	\parallel				1		\dashv						Z	×	×	96A	12-Jan-96
		+	\dashv		4	-					+	\dashv	ħ					×	×		95L	4-Dec-95
	294 294	1	4		-	-				\dashv	1	1	18	-				×	M		5 95K	12-Nov-95
		\dashv	_		4													<u> </u>	М		_	28-Oct-95
			×		Н				***									H		1	ᆫ	1-Aug-95
Comments	0	ס	M P	PE	OWP ML	Man. Temp. O	Joint M Fault Te		mt. Joint ev. Open.	ter Pvmt. ble Elev.	ost Water ot. Table	ost Frost Pt. 4-Pt.	up Frost 2-Pt.	Backup TDR	Backup TDR	Frost Volts	TDR	o. Rain	Temp.	Pvmt. Temp.	₹	Date dd/mmm/yy
	е	Profile	Distress	g		FWD Data	[W]	ı	• ।		Data	Manual Data	1			Data	MOBILE	MC	Data	ONSITE Data	c C	
Page 2 of 2																						
			_	P 58.3	MN (N	AKES,	ROITL	F DET	AST OI	LES E,	, 13 MI	.ANES	0 EB L	3, US-1	27SB - 271028, US-10 EB LANES, 13 MILES EAST OF DETROIT LAKES, MN (MP 58.3)	27SB						
																				l		

Notes

. 4

Denotes data collected and processed by Braun Intertec Corp

P Denotes data collected and processed by ERES Consultants, Inc.

Denotes data collected by Braun Intertec Corp.

X Denotes data collected by ERES Consultants, Inc.

Denotes data collected by Braun Intertec Corp. and processed by ERES Consultants, Inc.

M Denotes data collected by MN-DOT

Denotes data collected and processed by SME

Appendix B - SMP Data Sheets

• SMP-D10: SMP Field Activity Report

-

LTPP Seasonal Monitorin Data Sheet SMP-1	ng Program	Agency Code [2_7]					
Data Sheet SMP-I SMP Field Activity	Report	LTPP Section ID [1028]					
Ons	ite Datalogger a	and Instrumentation					
File Name - *.ONS	275B47KI	Comments:					
Battery Replace	Yes - No	Voltages (1.0					
Repairs/Calib.							
Other:							
	Mobile D	Datalogger					
File Name - *.MOB		Comments:					
TDR/Resistance Voltages	Sets (9 1)						
Other:							
	Manual Dat	ta Collection					
Piezometer	Yes - No	Comments:					
Resistance 2 pt.	Sets (4)						
Resistivity 4 pt.	Sets —						
Elevations	Sets (
Distress Survey	Yes - No						
Long. Dipstick Profile	Yes -(No)						
Photos or Video	Yes No						
Other:							
FWD and Associated Data							
FWD Testing	Sets —	Operator: DSP					
JCP - Snap Rings	Sets (AC					
JCP - Faulting	Sets ()	AC					
Other:							
TEREQUIRED, ATTACH SI	KETCHES TO	THIS DATA SHEET					
Prepared by: OFF		Employer: ERES/NCR Daylight Savings Time (Y or N): Y					



271028 - 27SB

<u>LOCATION</u> -US-10 EB Lanes, 13 Miles East of Detroit Lakes, MN (MP 58.3) <u>CONTACTS</u> -Joe Stegmaier (218) 847-1567, Dennis redding (218) 847-1575 <u>TEMP HOLES</u> - Sta 0-04, Depths are about 1.2", 6.0", and 8.2" (AC thickness = 8.5")

DISTRESS COMMENTS:

Sta	F1 -Tests at Sta 0-15, and at 25 foot intervals from Sta 0+00 to Sta 2+00.
Sia	$\frac{1}{1}$ - 10363 at 514 0-15, and at 25 100t intervals from 514 0 100 to 514 2 100.

- -15 LP NEXT TO INSTRUMENT HOLE AND L-TRANS, CR. BEHIND LP
- 125 M-TRANS.CR. 2' BEHIND LP AND M-TRANS.CR. 8" IN FRONT OF D7
- 175 M-TRANS.CR. 1' IN FRONT OF D7
- 200 M-TRANS.CR. 1' BEHIND LP
- <u>Sta</u> <u>F3</u> -Tests at Sta 0-30, 0-20, 0-10, AND AT 25 FOOT INTERVALS FROM sTA 0+00 TO sTA 2+00.
- -30 L-LONG.CR. DEVELOPING IN THE OWP BEHIND THE LP
- -20 D7 ON INSTRUMENTATION HOLE AND L-TRANS.CR. EXTENDS FROM SAW BETWEEN D6 AND D7
- -10 M-TRANS.CR. UNDER D7
- 125 M-TRANS.CR. 2' BEHIND LP AND 10" IN FRONT OF D7
- 200 M-TRANS.CR. 1' BEHIND LP

PIEZOMETER - Sta 1+00, 2.0 feet from edge of paved shoulder, Depth = 4.302M.

ELEVATIONS - Mn/DOT BM @ Sta. 0+00, 40 feet from edge of paved shoulder...

Offsets:	<u>PE</u>	<u>OWP</u>	<u>ML</u>	<u>IWP</u>	ILE
(M)	0.16	0.76	1.83	2.90	3.51
(ft)	0.5	2.5	6.0	9.5	11.5
	(nail)	(hole)	(hole)	(hole)	(hole)

Sta: Transverse profiles at Sta 0-30, 0-15, 0-10, and every 25 feet from Sta 0+00 to Sta 2+00 (None at Sta 0-20).

COMMENTS